

Ref	Date received	Description	Date Reported to Highways (or other body)	Date & Response From Highways or 3rd party if applicable	Completed /Closed
2018 001	03/01/18	<p>For Welshpool highways depot - The area around the Manse @ Velindre on B4390, has been flooding and some edges of the road in poor condition. During recent heavy rain the flooding near the caravan park on the Berriew Road was very severe, this is just below the previous repair work carried out March 2017, and it is deep, at night it is simply not visible, a number of people have complained and if you don't know it's there then there is a risk of a serious accident, was reported previously 1st March 2017 to highways Welshpool. The culvert just below the property called the Bushes at Pantyfrydd is badly blocked.</p> <p>From Berriew towards A483 a large pothole in middle of road just after the canal bridge, (Berriew Clerk informed)</p>	10/01/18	<p>12/2 : A highways grip cleaning gang has been along this stretch of road in recent weeks, road side gullies and grips were cleared so the running surface water good get off the road. HGSS supervisor will monitor the poor edge conditions of the road near the Manse and schedule repairs when required.</p> <p>The ponding issue Near the Caravan park will be investigated by HGSS Supervisor and remedial action scheduled.</p> <p>HGSS will arrange for the culvert below the Bushes Pantyfrydd to be cleared.</p> <p>As previously remarked in earlier correspondence Grips and gullies are continually cleared along the B4390, the road is also salted as a primary route.</p>	
2018 002	03/01/18	<p>Pot holes, several new severe pot holes have been evidenced and reported:- Deep one in middle of the road at B4390 Manafon between Laxford and Glas Cwm properties, Deep one in middle of the road on Llanfair Road between Cefnbach Lane/Belandeg, near the layby on the brow Deep one B4390 Manafon, almost opposite the church photo attached to highways email courtesy Cllr. Prentice</p> <p>General highways issues:-<i>these are repetitive issues</i> <i>There is still some flooding occurring between Manafon and the Green during periods of rain. Between Bronheulog B4390 to corner of Cross lane, been reported several times in the past but has been exceedingly dangerous during freezing weather and ice forming on road, the water is running fast down the road until it freezes, considered dangerous given the bend and junction location, this one has been in hand with highways since Jan 2017 and reported several other times</i> <i>B4390 from Tyn y Pant to Pantyfrydd, again in rain flooding has been bad, culverts and drains blocked, never seems to get solved properly,</i></p>	10/01/2018 & 31/1/18	<p>as at 25/1 & 31/1 no response from highways but the 2 potholes on B4390 in Manafon have been repaired. B4390 through Berriew resurfaced and appears the pothole on Llanfair road done.</p>	
2018 003	07/02/18	<p>Cllr. Benyon advised that even though the pot hole opposite church had been dealt with by highways he had received a number of complaints about the poor quality of the road surface, a number of residents have complained about the road noise and being woken several times in the early hours, particularly with heavy/farm traffic going through the village; Clerk to inform highways</p>	11/02/18	<p>12/2 highways manager advised: included this section of carriageway in the Capital programme bid for 2018-19. Provide this is confirmed by the PCC Cabinet repairs will be programmed and completed in the next financial year.</p>	
2018 004	05/02/18	<p>Please find attached photos, cause and consequence of flooding to property/land known as Lower House Farm Manafon. This brought to my attention by Mr Michael Woodroffe who owns the Rhiw Valley Light Railway who found the area used as a car park extensively waterlogged leaving people who were working on railway over weekend with now where to park. Mr Woodroffe pointed out two issues with highway adjoining the car park area .</p> <p>Firstly there is little or no verge to prevent or control the surface water running off the roadway allowing it to spill off road at a number of point .</p> <p>Secondly the drainage system/ layout on other side of highway is ineffective in draining the substantial area of roadway (Manafon side) , why is it ineffective ? the drains are set back off the roadway and over the years the original line of road has been encroached with a build-up of debris/soil /leaves so that the water simply flows past the drains before crossing the road and over spilling into car park area.</p>	05/02/18	<p>HGSS supervisor Paul Barr will investigate this issue and call to see Mr Woodroffe. If culverts and drains are blocked we will schedule cleaning works but it may be that with the quantity of rainfall and continued wet weather the drains and culverts don't have sufficient capacity.</p>	